

L208008

20-05-22 REV.01



leovince.com




International Customer Service:  
info@leovince.com

North America Customer Service:  
infousa@leovince.com - +1-844-536-7625



# ART 208008R

## LAMBDA WIRE EXTENSION HARNESS





# FOR YAMAHA TÉNÉRÉ 700 EURO 5

TYPE: DM11; A/01; A/03


**FITMENT NOTICE FOR NON-EUROPEAN COUNTRIES:**


Wire extension harness is required only if your O2 sensor is near the exhaust ports on motor.



NOTE / NOTES / REMARQUES /  
ANMERKUNGEN / NOTAS

NOTE / NOTES / REMARQUES /  
ANMERKUNGEN / NOTAS





NOTE / NOTES / REMARQUES /  
ANMERKUNGEN / NOTAS

